

November 7, 2014 Revised December 5, 2014 (Delete Mechanical/HVAC Items) Revised January 15, 2015 (Final)

Ms. Cathy Lauria Chief School Business Official West Northfield School District No. 31 3131 Techny Road Northbrook, Illinois 60062

RE: 10 YEAR LIFE SAFETY SURVEY

FIELD AND WINKELMAN SCHOOLS

PROJECT NO. 14126

Dear Cathy:

The following is the final summary of the Life Safety Items identified for Field and Winkelman Schools and associated estimated costs to perform replacement/repair of deficient items. After District review and authorization, a formal report, including updated safety reference plans, building descriptions and cost information will be submitted to the Illinois State Board of Education (ISBE) via the IWAS website.

FIELD SCHOOL

| <u>ITEM</u> | <u>DESCRIPTION</u> | BUDGET <u>AMOUNT</u> | COMPLETION |
|-------------|----------------------------------------------------------------------------------------------------------------|-------------------------|----------------|
| | ARCHITECTURAL | | |
| A1 | Perform miscellaneous roof flashing and metal coping repairs at roof/wall intersections and roof edge details. | \$ 25,000 | Within 5 Years |
| | PLUMBING | | |
| P1 | Replace existing wash fonts with new in the toilet rooms. | \$ 26,000 | Within 3 Years |

10 YEAR LIFE SAFETY SURVEY FIELD AND WINKELMAN SCHOOLS PROJECT NO. 14126 PAGE 2

| <u>ITEM</u> | <u>DESCRIPTION</u> | | | BUDGET <u>AMOUNT</u> | COMPLETION |
|---------------------------------------------------------------------------------|----------------------------------------------------|------------------------------------------------------------------------|------|---------------------------------------------------------------------------------|----------------|
| | ELECTRICAL | | | | |
| E1 | Emergency lightin | g revisions. 1964 Building | | \$ 3,500 | Within 3 Years |
| E2 | Illuminated exit sig | gnage. 1964 Building | | \$ 1,500 | Within 3 Years |
| E3 | Emergency lighting revision. 1965 - 1991 Additions | | | \$ 5,000 | Within 3 Years |
| E4 | Illuminated exit sig | gnage. 1965 - 1991 Additions | | \$ 2,000 | Within 3 Years |
| E5 | Replace entire exi buried PVC racew | sting buried primary conductor with neway. | w in | \$ 60,000 | Within 5 Years |
| E6 | Replace existing in | ntercom / master clock system with new | ٧. | \$ 110,000 | Within 5 Years |
| E7 | Replace old inefficients | cient exterior building lighting with new | LED | \$ 25,000 | Within 5 Years |
| FIELD COST SUMMARY Architectural Mechanical Plumbing Fire Protection Electrical | | Life Safety Item Sub-Total Contingency Fees TOTAL LIFE SAFETY | | 25,000 0 26,000 0 207,000 258,000 25,800 25,800 309,600 | |

WINKELMAN SCHOOL

| <u>ITEM</u> | <u>DESCRIPTION</u> | BUDGET <u>AMOUNT</u> | <u>COMPLETION</u> |
|-------------|-------------------------------------------------------------------------------------------------------|-------------------------|-------------------|
| | PLUMBING | | |
| P1 | Replace existing kitchen grease interceptor with new properly sized grease interceptor. 1980 Building | \$ 60,000 | Within 5 Years |
| | FIRE PREVENTION | | |
| FP-1 | Install heat trace to prevent freezing at entry vestibule fire sprinkler piping. 2002 Addition | \$ 6,500 | Within 3 Years |

10 YEAR LIFE SAFETY SURVEY FIELD AND WINKELMAN SCHOOLS PROJECT NO. 14126 PAGE 3

| <u>ITEM</u> | DESCRIPTION | | BUDGET <u>AMOUNT</u> | COMPLETION | |
|------------------|------------------------------------------------------------------------------------------------|----|-------------------------|----------------|--|
| | ELECTRICAL | | | | |
| E1 | Emergency lighting revisions. 1980 Building | | \$ 7,200 | Within 3 Years | |
| E2 | Illuminated Exit Signage. 1980 Building | | \$ 1,200 | Within 3 Years | |
| E3 | Emergency Lighting Revisions. 2002 Addition | | \$ 3,600 | Within 3 Years | |
| E4 | Illuminated Exit Signage. 2002 Addition | | \$ 600 | Within 3 Years | |
| E5 | Replace old, inefficient exterior building lighting with new LEI fixtures. Entire Building | D | \$ 30,000 | Within 5 Years | |
| E7 | Replace gymnasium and commons light fixtures with new energy efficient fixtures. 1980 Building | | \$ 102,000 | Within 5 Years | |
| | N COST SUMMARY | | | | |
| Architectural \$ | | \$ | 0 | | |
| Mechanical | | | (0.000 | | |
| Plumbing | | | 60,000 | | |

Life Safety Item Sub-Total

TOTAL LIFE SAFETY

Contingency

Fees

6,500 \$ 144,600

\$ 211,100

\$ 253,320

21,110

21,110

Sincerely,

ARCON Associates, Inc.

Fire Protection

Electrical

William M. Strejc, AlA Principal

WMS/dls

J:\1 D31\14126 10 Year Life Safety Survey\1 Docs\Corr\14126c004.wpd